



. . e-mail: [p.k.v.1@bk.ru](mailto:p.k.v.1@bk.ru)

## KOMATSU


### KOMATSU PC200 (PC100 PC100L-5 PC130 PC200LC-5 PW210-1)

	<b>205-939-7120</b> UG-PC200AD		1 450,00		
	<b>205-70-19570RC</b> UG-PC200RC TIP-ROCK CHISEL		900,00		
	<b>09244-02496</b> UG-PC200LOCK		143,00		


### KOMATSU PC300 (PC220 PC220LC-5 PC240LC-NLC PC280LC-3 PC290 PC300 PC360LC-3 PC380LC)

	<b>207-939-3120</b> UG-PC300AD		2200,00		
	<b>207-70-14151RC</b> UG-PC300RC TIP-ROCK CHISEL		1525,00		
	<b>09244-02516</b> UG-PC300LOCK		150,00		

**KOMATSU PC400** (PC400 PC400LC-5 PC450 PC450LC)


					
	<b>208-939-3120</b> UG-PC400AD		3300,00		
	<b>208-70-14270RC</b> UG-PC400RC TIP-ROCK CHISEL		2490,00		
	<b>09244-03036</b> UG-PC400LOCK		200,00		

**KOMATSU PC650** (PC650 PC650LC-3 PC650SE PC750 PC750SE)



					
	<b>209-70-54210RC</b> UG-PC650RC TIP-ROCK CHISEL		4625,00		
	<b>09244-03036</b> UG-PC650LOCK		878,00		

**HYUNDAI**



**HYUNDAI R200** (R180 / 170W-7A / 200LC / 200W / 210LC)

					
	<b>61N6-31320</b>		1535,00		
	<b>61N6-31310</b> UG-R200		1067,00		
	<b>E161-3035</b> UG-R200PIN		111,00		
	<b>61E5-11150</b> UG-R200Lock		59,00		



**HYUNDAI R300** (R290 / 305LC-7 / 320LC-7 / 320LC-7A)

 					
	<b>61N8-31310</b> UG-R300		1450,00		
	<b>E262-5004</b> UG-R300PIN		117,00		
	<b>61E5-11150</b> UG-R300Lock		72,00		


**HYUNDAI R360** (R360 / 360LC-7 / 360LC-7A)

 					
	<b>61NA-31310</b> UG-R360		2050,00		
	<b>61E7-0105</b> UG-R360PIN		137,00		
	<b>61EH-11150</b> UG-R360Lock		78,00		

**HYUNDAI R450** (R450 / 450LC-7 / 450LC-7A / R500LC-7 / R500LC-7A)


 					
	<b>61NB-31310</b> UG-R450		3235,00		
	<b>61E7-0105</b> UG-R450PIN		137,00		
	<b>61EH-11150</b> UG-R450Lock		78,00		

### HYUNDAI R470 (R470 / R500)


					
	<b>66NB-31310</b> UG-R470		3350,00		
	<b>66NB-</b> UG-R470PIN		124,00		
	<b>66NB-</b> UG-R470Lock		72,00		

### HITACHI



#### HITACHI EX 100

					
	<b>30S (Z963228)</b>		463,00		
	<b>30S RUBBER &amp; PIN (SET)</b>		120,00		



#### HITACHI EX 200

					
	<b>35S</b>		795,00		
	<b>35S RUBBER &amp; PIN (SET)</b>		137,00		




### HITACHI EX 300

					
	<b>40S</b>		1170,00		
	<b>40S RUBBER &amp; PIN (SET)</b>		155,00		


### HITACHI EX 400

					
	<b>45S</b>		1405,00		
	<b>45S RUBBER &amp; PIN (SET)</b>		225,00		


### DOOSAN S200

  	<b>2713-1218</b> UG-S200-5AD		1515,00		
	<b>2713-1217</b> UG-S200-5TIP		1045,00		
	<b>2705-1020</b> UG-S200-5 PIN		115,00		
	<b>2114-1848</b> UG-S200-5 Was		58,00		

## DOOSAN S300

	<b>2713-1220</b> UG-S300-5AD		1875,00		
	<b>713-00054</b> UG-S300-5TIP		1215,00		
	<b>2705-1021</b> UG-S300-5 PIN		128,00		
	<b>2114-1849</b> UG-S300-5 Was		78,00		

## DOOSAN S420

	<b>2713-1273</b> UG-S470-5AD		3675,00		
	<b>2713-1236</b> K1004145 UG-S470-5TIP		2430,00		
	<b>2705-1034</b> UG-S470-5PIN		150,00		
	<b>2114-1931</b> UG-S470-5W		85,00		

## CAT

<b>9W8309/1U3302</b>	778,00		
<b>9W2359/ 1U3352</b>	1045,00		
<b>6Y5409/ 7T3402</b>	1570,00		
<b>1U3452/9W8452</b>	1955,00		
<b>1U3552/ 9W8552</b>	3285,00		